



## REVIEW of SUPPLEMENTS to CR-MM-1-0-00

### DESCRIPTION AND OPERATION

#### 1. **General**

This Chapter contains supplementary information on the optional equipment which is installed in the airplane.

The information given in this Chapter complete or supersede the basic Maintenance Manual in those sections as specified. Where not otherwise stated, information shown in the basic Maintenance Manual remains effective. Each Supplement consists of a Title Page, Record of Revisions, List of effective pages and the proper text.

#### 2. **List of supplements**

No.	Content	Note
01	Inspection and / or replacement of the valve push-rod-assy. for ROTAX® Engine Type 912 (Series)	Minor Change approval No.10063870 24 November 2018
02	New type of Kuntzleman landing light holder (SI0664N clip replaced by SI0670N bracket)	Minor Change approval No.10065405 2 May 2018
03	Installation of Dynon SkyView System with the SV-HDX1100 display in the PS-28 Cruiser airplane	Major Change approval No.10066844 11 September 2018
04	New cockpit upholstery design of PS-28 Cruiser	Minor Change approval No.10066801 7 September 2018
05	Improved canopy guidance during closing	Minor Change approval No.10067522 15 November 2018
06	Modification of engine lower cowling for efficient cooling	Minor Change approval No.10071145 07 Oct 2019
07	Replacement of carburetor circlip for Rotax® engine type 912 (Series)	Minor Change approval 10071433 30-Oct-2019



### 3. List of airplane S/N covered by the supplement

Airplane model	Serial No.	Supplement. No.	Note
PS-28 Cruiser and SportCruiser / PiperSport – operating under EASA	C0589, C0590, C0601, C0602, C0603, C0604, C0605, C0606, C0607	01	Valid also for all aircraft the engine of which have been equipped with valve push-rod assy. part no.854861 during engine repair, maintenance or general overhaul as of May 01 to 30 November 2017, inclusive.
PS-28 Cruiser and SportCruiser / PiperSport – operating under EASA	From S/N C0644 inclusive	02	Valid also for all airplanes the owners of which decide to replace the original Kuntzleman landing light holder by the new holder type
PS-28 Cruiser and SportCruiser / PiperSport – operating under EASA rules	From S/N C0644 inclusive	03	Valid also for the airplanes the owners of which decide to replace the original SV-D1000 by the new SV-HDX1100 display
PS-28 Cruiser and SportCruiser/PiperSport – operating under EASA rules	All airplanes with the new cockpit upholstery design	04	New upholstery design is an optional equipment
PS-28 Cruiser and SportCruiser/PiperSport operating under EASA rules	From S/N C0660 inclusive	05	Valid also for the airplanes the owners of which decide to install the improved canopy guidance
PS-28 Cruiser and SportCruiser/PiperSport operating under EASA rules		06	Valid also for the airplanes with installed bulletin SB-CR-067 the owners of which decide to replace the original engine lower cowling by the modified one, dwg.SE0562N
PS-28 Cruiser and SportCruiser/PiperSport operating under EASA rules		07	ROTAX Service Bulletins no. SB-912-073 UL, no. SB-912-073 Service Bulletin no. SB-CR-075